




PAROS



1




2




3




4



5



6



1	1X
2	1X
3	2X
4	2X
5	1X
6	4X



A

M6x20mm



16x

B

Φ13mm



2x

C

M6x50mm



2x

D

Φ23mm



2x

E


4mm



1x


I.

1



C	M6x50mm
	2x
D	Φ23mm
	2x
B	Φ13mm
	2x
E	4mm
	1x
	75%



2




A	M6x20mm
	8x
E	4mm
	1x
	75%

II.


3




4



5




6




IV.

7



8



**LE TRI
+ FACILE**



Séparez les éléments avant de trier