

Barry



D Montageanleitung

GB Assembly instructions

FR Notice de montage

NL Handleiding voor de montage

CZ Montážní návod

IT Istruzioni di montaggio

RO Instrucțiuni de montaj



RU инструкция по сборке

PL Instrukcja montażu

SK Návod na montáž

HU Szerelési útmutató

TR Montaj talimati



Service • Assistenza • Dienstverlening • Serwis Servis • Szerviz • Сервисная служба

Name • Nom • Nome • Naam
Nazwa • Jméno • Názov • Név
Denumire • İsim • Название




Barry EB

Nr. • No. • N° • Номер • Č • Sz

SH51

Typ • Type • Tip • Típus • Tipo
Тип

OHNE



A	B	C	D	E	F	G	H
4x	4x 8x50	4x 10x80	4x 8x20	2x	2x 8x60	2x 8x40	2x M8

Service • Assistenza • Dienstverlening • Serwis Servis • Szerviz • Сервисная служба

Name • Nom • Nome • Naam
Nazwa • Jméno • Názov • Név
Denumire • İsim • Название




Barry EB

Nr. • No. • N° • Номер • Č • Sz

SH51

Typ • Type • Tip • Típus • Tipo
Тип


LARO





A	B	C	D	E	F	G	H
4x	4x 8x50	4x 10x80	4x 8x20	2x	2x 8x60	2x 8x40	2x M8




A	B	C	D
4x	4x 8x50	4x 10x80	4x 8x20







Achtung! Schrauben nicht überdrehen		GB	Watch Out! Do not over tighten
FR	Attention! Ne serrez pas trop	NL	Let Op! Niet te vast
CZ	Dávej Pozor! Nepřetahujte	IT	Attento! Non stringere
RO	Ai Grijai! Nu strângeți	RU	Осторожно! Не затягивайте
PL	Uważaj! Nie dokręcać zbyt mocno	SK	Dávaj Pozor! Nepreťahujte
HU	Vigyázz! Ne húzza túl	TR	Dikkat! Üzerinde sıkmayın
F		H	
2x 8x60		G	
		2x 8x40	2x M8



KT_2xSchloss_8x60