



Coos




- | | |
|----------------------------------|---------------------------------------|
| D Montageanleitung | GB Assembly instructions |
| FR Notice de montage | NL Handleiding voor de montage |
| CZ Montážní návod | IT Istruzioni di montaggio |
| RO Instrucțiuni de montaj | RU инструкция по сборке |
| PL Instrukcja montażu | SK Návod na montáž |
| HU Szerelési útmutató | TR Montaj talimati |



**Service • Assistenza • Dienstverlening • Serwis
Servis • Szerviz • Сервисная служба**


Name • Nom • Nome • Naam Nazwa • Jméno • Názov • Név Denumire • İsim • Название	Coos DB	
Nr. • No. • N° • Номер • Č • Sz	SH50	
Typ • Type • Tip • Típus • Tipo Тип	BS G	




A	B	C	D	E	F	G	H
4x	4x 8x45	4x 8x20	12x 8x40	8x	8x 8x50	8x 8x60	8x M8





A		4x			
B		4x 8x45			
C		4x 8x20			
D		4x 8x40			
E		8x			
F		8x 8x50			





3.

Achtung! Schrauben nicht überdrehen	GB Watch Out! Do not over tighten
FR Attention! Ne serrez pas trop	NL Let Op! Niet te vast
CZ Dávej Pozor! Nepřetahujte	IT Attento! Non stringere
RO Ai Grija! Nu strângeți	RU Осторожно! Не затягивайте
PL Uwaga! Nie dokręcać zbyt mocno	SK Dávaj Pozor! Nepretahujte
HU Vigyázz! Ne húzza túl	TR Dikkat! Üzerinde sıkmayın

G		H	
8x 8x60	D	8x 8x40	8x M8
	