









Ron



1	1X	1/1
2	1X	1/1
3	4X	2/2



2/2

A

M8X8

B


Ø18xØ8x1.5

C

Ø20

D

5MM




16x



16x




8x





1x



I.

1




A	M8x8
	16x
B	Ø18xØ8x1.5
	16x
D	5MM
	1x
	

2



II.

3




C







Ø20

8x



4



LE TRI
+ FACILE



Séparez les éléments avant de trier