






Art. Nr. 8950 0000









LKZ 41164



- | | |
|----------------------------------|------------------------------|
| (D) Montageanleitung | (GB) Assembly instructions |
| (FR) Notice de montage | (IT) Istruzioni di montaggio |
| (NL) Handleiding voor de montage | (PL) Instrukcja montażu |
| (CZ) Montážní návod | (SK) Návod na montáž |
| (HU) Szerelési útmutató | (RO) Instrucțiuni de montaj |
| (TR) Montaj talimatı | (RU) Инструкция по монтажу |





A 090913  7x32 x28	B 000146  15x12 x28	C 100640  20x0.5 x8	D 000151  10x35 x60	E 135021  x16	F 000759  3x20 x16
G 155999  x1	H 013859  8x40 x1	I 000754  3.5x16 x2	J 090185  4.5x45 x1	K 053728  x6	L 093469  x6
M 010942  4x16 x12	N 101777  70x50 x3	O 002152  L550 x4	P 000762  3.5x13 x4	Q 000767  3x13 x32	R 170390  x2
S 189554  x6	T 005960  M4x25 x6	U 076884  x4	V 000126  x2	W 030579  x16	X 235593  6x8 x24




N	Size/MaB (mm)	Qty	✓	N	Size/MaB (mm)	Qty	✓
1A	2062x596x16	1		11	1030x635x38	1	
2A	2062x596x16	1		12	952x572x16	1	
3	550x170x12	4		13	952x572x16	1	
4	550x170x12	4		14	1468x488x16	1	
5	419x170x12	4		15	1468x488x16	1	
6	984x65x16	2		16	2073x480x3	2	
7	980x224x16	2		17	547x429x3	4	
8	952x200x16	1		18	L=947	1	
9A	515x572x16	1		19	L=2060	1	
10	1030x635x38	1					

Service - Dienstverlening - Serwis - Servis - Сервисная служба

Name - Naam - Nazwa - Isim - Название








Nr. - No. - Номер

Typ - Type - Tip - Тип






1




A 090913 7x32 x12	B 000146 15x12 x8	D 000151 10x35 x8	L 093469 x6	O 002152 L550 x4	P 3.5x13 x4
Q 000767 3x13 x4	R 170390 x2	W 030579 x16	X 235593 6x8 x12		





2





3




4






5







6




x2




7



8




x2





9

x2



10

x2



11








Figure 1 consists of two circular diagrams. Diagram (a) on the left shows a hand holding a stylus with a force transducer, positioned over a target. An arrow indicates the direction of movement. Diagram (b) on the right shows the target area with a central point 'c' and a surrounding circular region.


0

x4






10




14



15




16






17

L1=L2



135021		x16
000759		3x20 x16
101777		70x50 x3






19

155999


G



x1

013859

H



8x40

x1

000754

I



3.5x16

x2

090185

J



4.5x45

x1

