

STEVINSON 3DL



LKZ 042289



D Montageanleitung

FR Notice de montage

NL Handleiding voor de montage

CZ Montážní návod

HU Szerelési útmutató

TR Montaj talimatı

GB Assembly instructions


IT Istruzioni di montaggio




PL Instrukcja montażu

SK Návod na montáž




RO Instrucțiuni de montaj

RU Инструкция по монтажу





A	M 6x50	B	M 6x25	C	M 6x40	D	H 100	E	38	F	H 42	G	4
	x2		x8		x4		x5		x9		x4		x1
H		x4	I	M 6x30		x8							




1






2



3






4





E	38	F	H 42	G	„4“	I	M 6x30
	x2		x2		x1		x4







5



6



A	M 6x50	G	„4“
	x2		x1



Service • Assistenza • Dienstverlening • Serwis •
Servis • Szerviz • Сервисная служба



Name • Nom • Nome • Naam •
Nazwa • Jméno • Názov • Név •
Denumire • Isim • Имя

STEVINSON

Nr • No. • N° • Номер • Č • Sz

Typ • Tipo • Тип • Typ •
Тип • Тр

3DL



A	M 6x50	B	M 6x25	C	M 6x40	D	H 100	E	38	F	H 42	G	„4”
	...		...		...		...		...		...		...
H		I	M 6x30										
	...		...										