






# Unterschrank

Nr. 016 Rev.01






<b>90</b> 6x 					
<b>78</b> 3x links 	<b>79</b> 3x rechts 	<b>22</b> 4x 	<b>36</b> 56x 3,5 x 16 	<b>23</b> 4x 	<b>21</b> 3x 
<b>27</b> 24x 3,0 x 20 	<b>63</b> 4x 8 x 30 	<b>91</b> 4x 	<b>26</b> 6x 4,0 x 30 M4 	<b>70</b> 1x LEIM GLUE 	<b>106</b> 4x 4,0 x 30 




1

<p>79</p>  <p>3x rechts</p>	<p>78</p>  <p>3x links</p>	<p>36</p> <p>3,5 x 16</p>  <p>18x</p>
		<p>63</p> <p>8 x 30</p>  <p>4x</p>




2

<p>22</p>  <p>4x</p>	<p>70</p>  <p>1x</p>
---	---







3

<b>27</b>	3,0 x 20
24x	
<b>23</b>	
4x	






4 2x

<b>26</b>		<b>36</b>	3,5 x 16
4x	4,0 x 30 M4	8x	
<b>90</b>		<b>91</b>	
4x		4x	
		<b>21</b>	
		2x	




5



<p><b>26</b>  4,0 x 30 M4</p> <p>2x</p>	<p><b>36</b>  3,5 x 16</p> <p>4x</p>
<p><b>90</b> </p> <p>2x</p>	<p><b>21</b> </p> <p>1x</p>


6 2x

<p><b>36</b>  3,5 x 16</p> <p>12x</p>
--




7 2x

36 3,5 x 16  
8x



8

36 3,5 x 16  
6x



9

106

4,0 x 30



4x

