


REPC-Nr.:

Service • Assistenza • Dienstverlening • Serwis
Servis • Szerviz • Сервисная служба




Artikel.-Nr.:

0841-KO_02-50

Montageanleitung.-Nr.:

MA1-00435



SCAN ME

Das Ersatzteil-Anforderungsformular finden Sie auf
The replacement parts requisition form you find on
<https://www.maeusbacher.de/ersatzteile/>

BT1-00521 Colli 1/1


| | | | |
|--------------------------|------------------------|-------------------------|------------------------|
| B02-10 4x ø15x12mm | B02-20 4x | B01-200 8x 6,3x13 | B01-10 4x 6,3x50 |
| B01-327 4x M4x19 | B01-330 4x M4x10 | B05-130 1x Leim | |

BT1-00005 Colli 1/1

| | |
|---------------|-------------------------|
| B02-173 4x | B01-123 8x 4,0x15 |
|---------------|-------------------------|











BT1-00522 Colli 1/1


| |
|---------------|
| B06-545 2x |
|---------------|




SCAN ME

Colli 1/1








1






2



3





4








3

| | | | | |
|--|---------------|--------------------------------------|----------------|----------------------|
| | B02-10 | | B01-200 | |
| | 4x | $\varnothing 15 \times 12 \text{mm}$ | 8x | 6,3 \times 13 |




4


| | | | | | | |
|--|--------|--------|---------|--|---------|--------|
| | B01-10 | | B02-173 | | B01-123 | |
| | 4x | 6,3x50 | 4x | | 8x | 4,0x15 |



5




1



180°

2



3

