













TOKIO T




1	2X	900X700X36	1/3
2	1X	900X400X36	2/3
3	1X	1044X710X18	2/3
4	2X	1042X54X18	2/3
5	2X		3/3
6	2X		3/3
7	1X		3/3
A3	2X	L=850	2/3

 2/3	AA  Ø8x30 mm 8x	AC  Ø7x50 mm 8x	PS  Ø12 mm 8x	OA  4 mm 1x	MC  Ø8 mm 8x
MD  Ø8 mm 8x	BH  Ø4x16 mm 52x	KI  40x16x22 mm 4x	SN  Ø20x2 mm 4x	 3/3	A  M8x16 mm 8x
B  M8x10 mm 4x	C  Ø18xØ8x1,5 mm 8x	D  M8x12 mm 8x	E  5 mm 1x	F  6 mm 1x	G  8 mm 1x

I.




1.



AA $\varnothing 8 \times 30$ mm
8x


BH $\varnothing 4 \times 16$ mm
24x

2.




D M8x12 mm
8x

G 8 mm
1x




II.

3.




AC	Ø7x50 mm
	8x
PS	Ø12 mm
	8x
OA	4 mm
	1x

4.




KI	40x16x22
	4x
BH	Ø4x16 mm
	8x




III.

5.




6.



IV.

7.



B M8x10




4x


F 6 mm




1x



8.



A M8x16



8x

E 5 mm




1x

C Ø18xØ8x1,5





8x





V.



9.



F 6 mm
1x








10.



VI.

11.



LE TRI
+ FACILE



BAC
DE
TRI

Séparez les éléments avant de trier