

Assembly instruction Stressless® Home Office

Steel base



5x
1997303



4x



1x
1997213










2x
990002626




2x
1997304


1x
1997000




990002271




7




8



9



10



11



12

