






Carlos CT



①




②



③



④



1	1x
2	2x
3	2x
4	2x



1/1

A

M6x10mm



16x

B

M6x30mm



6x

C

Φ16xΦ6x1mm



22x

D

M4



1x

I.

1

A M6x10mm 16x

C $\Phi 16x\Phi 6x1mm$ 16x

D M4 1x

75%

2

B M6x30mm 6x

C $\Phi 16x\Phi 6x1mm$ 6x

D M4 1x

75%

3

D M4 1x

100%

LE TRI + FACILE

Séparez les éléments avant de trier

BAC DE TRI